MR3287-12 Serial No. 10/773,399 Response to Office Action dated 4 August 2004

<u>REMARKS</u>

The title of the present invention is now amended to be "SCREW WITH CUTTING EDGES".

Claim 1 is rejected under 35 U.S.C. 102 (b) as being anticipated by Williams and Meersteiner '336. Both Williams and Meersteiner '336 disclose a screw with a head and a shank, and the threads on the shank include slots and the slots are beveled. Nevertheless, it is noted that the slots in both of Williams and Meersteiner '336 are arranged to be spiral relative to the longitudinal axis of the shank. On the contrary, as disclosed in the claimed screw, the slots are arranged along the longitudinal axis of the shank and can be clearly seen from Fig. 4 of the present application. This is totally different from those slots disclosed by both Williams and Meersteiner '336.

Besides, the so called cutting edges on the remaining thread sections in the disclosure by Meersteiner form a triangular surface which perpendicularly extends from the shank; this fact can also been seen from Fig. 3 of Meersteiner. When threading into an object, the triangular surfaces of Meersteiner lack efficient cutting edges to cut the object as the cutting edges 536 disclosed in the claimed screw. The triangular surfaces would impede cutting into the objects when

MR3287-12 Serial No. 10/773,399 Response to Office Action dated 4 August 2004

threading the screw of Meersteiner into objects.

Williams discloses a similar structure with the screw of Meersteiner, wherein the slots, as shown in Fig. 3, are arranged to be inclined relative to the longitudinal axis of the shank.

Obviously, Williams and Meersteiner both disclose a screw that has spiral and inclined slots along the longitudinal axis of the shank, and the slot arrangements in the claimed screw are axial. The disclosures by Williams and Meersteiner cannot anticipate the claimed application due to this significant difference. Therefore, the amended claim 1 makes the claimed invention more distinguishably patentable over the prior art cited by the Examiner. It is believed that the amended claim 1 has disclosed a structure whose construction and function are quite different from and patentably distinguishable over the cited prior arts. Therefore, it is believed that, the rejections under 35 U.S.C. 102 (b) should be removed, and the amended claim 1 should be allowable.

In view of the foregoing amendments and remarks, Applicant submits that the application is now in a condition for allowance and such action is respectfully requested.

MR3287-12 Serial No. 10/773,399 Response to Office Action dated 4 August 2004

It is respectfully noted that this Amendment and Response was prepared by the Applicant and it has merely been corrected for form and is being filed by the undersigned attorney.

Respectfully submitted,

For: ROSENBERG, KLEIN & LEE

morton g.

Morton J. Rosenberg Registration No. 26,049

Suite 101 3458 Ellicott Center Drive Ellicott City, Maryland 21043 Telephone: 410-465-6678

CERTIFICATE OF FACSIMILE TRANSMISSION

I hereby certify that this paper is being facsimile transmitted to the U.S. Patent and Trademark Office, Art Unit #3677, facsimile number 703-872-9306 on the date shown below.

For: ROSENBERG, KLEIN & LEE

Morton J. Rosenberg

Motorion 1. Rosemberg

Date: 11./4/04

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not infinited to the norms encored.
□ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
COLOR OR BLACK AND WHITE PHOTOGRAPHS
GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
Потиер.

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.